

Troubleshooting Balance Problems:

1. Verify that the problem is in the PAT-4, not the source, or the amp/speaker that the PAT-4 drives. Here's a pretty solid method, as it changes only one thing. If there is a level difference, between test 1a and test 1b, then it is certainly a PAT-4 issue:

